

Coberley Parish – Highways issues requiring resolution

For Parish Council Meeting, 7 November 2019:

1. A436 Cowley/Ullenwood crossroads.
 - a) Local residents claim road is noisier since being resurfaced. ACTION: Can GCC explain this? Further discussion needed Cllr DM & DT.
 - b) Reflectors beside Old Ullenwood Lodge (formerly South House) - one broken reflector still to be replaced. ACTION: GCC to replace. Outstanding
2. Ullenwood Manor Road and Hartley Lane where Cotswold Way shares highway. Cotswold Way signage needed directed at vehicles. – Meeting held by Cllr McGaw with Mike Barton GCC PROW Officer and Becky Jones Cotswold Conservation Board Trails and Access Officer 16 Jan 2019. They were to investigate whether a solution suitable for use throughout the Cotswold Way could be created. ACTION: Mike Barton & Becky Jones. Conclusion awaited.
3. Public footpath crossing A436 (Hartley Bottom – Coberley village) west of Seven Springs. Cllr McGaw has asked Mike Barton GCC PROW Officer to arrange 'pedestrian crossing' signs either side to alert on-coming traffic. ACTION: Mike Barton Conclusion awaited
4. '20 is Plenty' signs for Coberley Road. To be swapped between Ullenwood Manor Road and Coberley Road. Additional signs will be needed. ACTION: Danny Taylor to provide PC with 5 signs. DT requested from A Parker-Mowbray. Awaited.
5. Damaged signpost at junction to Upper Coberley, directly opposite Cowley junction, on A435. ACTION: GCC to arrange repair. DT advised corrected twisted sign. Cllr JT has provided photo of damaged sign referred to.
6. Damaged sign on A435 at Upper Coberley junction (Slacks Barn) approaching Seven Springs. ACTION: GCC to repair DT cannot identify issue. Cllr JT has sent photo.
7. Upper Coberley road. Drainage grips between Upper Coberley Farm and the top cottages, need clearing. (near the red and white marker poles in the banks marking the gas pipes underground). ACTION: GCC to arrange clearance DT arranged to re-cut grips. Cllr JT advised grips made but not dug in far enough to take water into the field, so not working.
8. Upper Coberley road (from A435 Cowley junction). Earth bund created. Verge soil eroding. Danger to vehicles on edge of tarmac. ACTION: GCC to investigate and rectify. DT arranged surfacing and to cut grips through bund. Cllr JT advised name of landowner.
9. Ongoing erosion of the verge on Hartley Lane that has occurred since the road was resurfaced (similar issue to item 8), lifting the metalled surface above the level of the verge alongside. We are now seeing the highway beginning to break up along its edge, and it is considered that both problems will become exacerbated as time goes on unless action is taken. A site meeting is recommended. ACTION: GCC
10. Roadside drain blocked at Hartley Farm. ACTION: GCC